

10K BLENDER EMERGENCY SHAFT REBUILD

**TOTAL SAVINGS:
OVER \$65,000**

Background:

- Shaft damage due to bearing issue.
- Shaft was removed, standard replacement lead time 4-6 weeks with an additional requirement to purchase in sets.
- Plant Manager believed having equipment down for this length of time would decrease production by half as other blender is 6K.
- Malloy repaired the shaft and checked for stress welds, returning to customer within 48 hours.

